

Marquage résistances

chiffres significatifs

1	••
1,25	•
1,5-1,6	•—
2	•
2,5	
3-3,2	—
4	—•
5	—
6,4-7	— —
7,5-8	•••

multiplicateur

x10	⋮
x100	⋮
x1k	— •
x10k	==
x100k	T
x1M	⌋

exemples

1k	••— •
3,2k	— •
15k	•— ==
50k	— ==
64k	— — ==
100k	••T
200k	•T
500k	— T
700k	— —T
1M	••⌋